




# SB stub arbor

BT / SK

● Min. 80% taper fit



L1=3,5,7,8,10,12

Taper	Code No.	H1	$\phi C$	W	G
BT40(SK40)	BT40-SB27-075	32	40	7	M24
BT50(SK50)	BT50-SB32-090	41	46	8	M30